Oil Field Environmental Incident Summary

Responsible Party: OXY USA Inc. **Well Operator:** OXY USA INC. **Well Name:** GRIGGS 2-8-9H-142-97

Field Name: WILLMEN Well File #: 22197

Date Incident: 12/7/2012 Time Incident: 1000 Facility ID Number:

County: DUNN Twp: 142 Rng: 97 Sec: 8 Qtr: NW NW

Location Description:

Submitted By: Terry Ryland Received By:

Contact Person: Terry Ryland

5 GREENWAY PLAZA STE 110 HOUSTON, TX 77046-0506

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:1 MilesDistance Nearest Water Well:1 Miles

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units	
Oil	8	barrels	0	barrels	8	barrels	
Brine	2	barrels	0	barrels	2	barrels	
Other	0	barrels	0	barrels	70	barrels	

Description of Other Released Contaminant:

Inspected: Written Report Received: 2/11/2013 Clean Up Concluded: 2/9/2013

Risk Evaluation:

Top soil in berm around tanks

Areal Extent:

Potential Environmental Impacts:

Soil within the berm area

Action Taken or Planned:

OXY is responding to the incident with the intent to truck offsite oil and water from the full storage tanks and put any recovered material back into the tanks.

Wastes Disposal Location: Oil and water recovered will go back into the tanks onsite.

Agencies Involved:

Updates

Date: 12/7/2012 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release remained on location, within dike, according to report.